

Portable Hardness Tester



dmeq

QH5 Models D / G / M

S.I. Instruments
256 South Rd. Hilton
South Australia 5033
Ph (08) 8352 5511

info@si-instruments.com.au
www.si-instruments.com.au

www.demeq.com

QH5 User Manual

Portable Hardness Testers

P/N: QHD501 – ENG – Rev 4 – 2020

Index

Chapter 1	First steps	
1.1	Know the QH5	1
1.1.1	Front panel	2
1.1.2	Connectors	2
1.2	Install or replace batteries	3
1.3	Connecting the impact device	5
1.4	Using the impact device	6
1.4.1	Loading the impact body	6
1.4.2	Release and measure	6
1.5	The "Q" key	7
1.6	Display illumination and contrast	7
1.6.1	Display backlight illumination	7
1.6.2	Display contrast	8
1.7	Locking and unlocking the keypad	8
Chapter 2	Measuring with the QH5	
2.1	Numerical measure screen (Normal)	10
2.1.1	Screen mode-1 (Datalogger)	10
2.1.2	Screen mode-2 (Material)	11
2.1.3	Screen mode-3 (Statistics)	11
2.2	Keys in numerical measure modes	12
2.3	Graphic measure screen (Histogram)	14
2.4	Keys in the graphic measure screen mode	15
2.5	Set impact device angle	16
2.6	Select material and hardness unit	17
Chapter 3	Menu system and editing	
3.1	Instructions on using the menu system	19
3.1.1	Text editor	20
3.2	Main menu	22
3.2.1	Change hardness unit	22

	3.2.2	Alarm settings	23
	3.2.3	Set histogram range	24
	3.2.4	Select language	24
	3.2.5	Unit information	25
3.3		General configuration options	25
	3.3.1	Set time and date	26
	3.3.2	Set time and date format	26
	3.3.3	Set keypad sensitivity	26
	3.3.4	Set auto-off time	28
	3.3.5	Adjust display contrast	28
	3.3.6	Beep activation	29
	3.3.7	Introduction screen	29
	3.3.8	Owner information	29
	3.3.9	Lock configuration options	31
	3.3.10	Model upgrade licenses	32
	3.3.11	Return to factory default settings	33
3.4		Measuring configuration options (Hardness)	34
	3.4.1	Set impact device angle	34
	3.4.2	Select material	35
	3.4.3	The "Plus" key	35
	3.4.4	Set group (N) number	36
	3.4.5	Select measure mode	37
	3.4.6	Create custom or user units	37
	3.4.7	Select impact device type	41
	3.4.8	Set alarm for impact device tip	42
	3.4.9	Return to factory default settings	42

Chapter 4 Using the Datalogger

4.1	How data is organized	43
4.2	Memory menu	44
4.3	Creating a file	44
4.4	Actions over single files	45
4.4.1	View data in a single file	46
4.4.2	The “Q” key in a grid	47
4.4.3	The “Q” key in a histogram	48
4.4.2	Send data from a single file	48
4.4.3	Rename a file	49
4.4.4	View file size	49
4.5	Actions over all files	49
4.5.1	Send all files	49
4.5.2	Erase all files	49
4.6	Quick memory menu (Mem key)	50
4.7	Connecting to PC with DataCenter	51
4.8	Datalogger configuration	52
4.8.1	Configure communications	52
4.8.2	Capture modes	54
4.8.3	Advanced configuration	54

Appendix

Tips on how to measure correctly

Technical specifications

Additional information

Unit maintenance
 QH5 accessories
 Error messages
 Proper disposal
 Our website: www.demeq.com
 Technical Support

Thank you choosing dmq

And thank you for purchasing a QH5 rebound hardness tester.

Company Statement

At dmq we develop, manufacture and distribute software and quality control instruments offering innovation and solutions that come as a direct result of listening to your needs as a user. We apply some of the latest technology available in the industry to build instruments that are robust, precise and easy to operate.

We are convinced that our products would not be complete without permanent technical and after sales support. So in addition to a great product we offer:

- Quick answers to your inquiries.
- Unlimited access to technical information as well as application notes.
- Special offers for registered customers.
- Firmware and software upgrades at no charge.
- Attention to your inquiries and suggestions.

We hope that the QH5 will meet and exceed your application needs.

General information

Models included in this manual

The information included in this manual applies to QH5 series portable hardness testers including models D, G and M.

Registered trademarks

dmq is a registered trademark of demeq S.R.L and its affiliate companies.

Important notice

The information contained in this manual is intended to educate users on the operation of the QH5 impact hardness testers. Failure to read and understand this manual can lead to measurement errors. Decisions based on measurements and or results that are erroneous can lead to property damage, personal injury or even death. Demeq S.R.L assumes no responsibility as a result of the improper use of our instruments.

Applicable standards

- ASTM A956

User training

Correct use of an impact hardness tester requires that you take all of the following into consideration:

- Select the instrument as well as the impact device that is best suited for your application.
- Know the specific requirements for the test you will be conducting.
- Make sure that the person operating the unit has been trained on its use.

This manual provides all of the information needed to configure and operate the QH5 hardness tester. However there are additional factors that can affect tests done with this instrument. Specific information on those factors is outside the scope of this manual. When in doubt you should always seek expert advice or refer to specific textbooks on portable hardness testing. Additional information can also be found on the internet and through local government agencies as well as in technical institutes.

Measuring Principle

QH5 D, G and M models operate on the Leeb impact rebound method where the ratio between the impact and rebound velocities that is released on the test piece is measured to establish a Leeb hardness value. The step by step process is represented in figure 1 as follows: 1, the impact body is released and travels inside the impact device; 2, the impact body tip hits the test piece; 3, the impact produces a rebound.




Figure 1: Representation of the Leeb rebound method

The measured Leeb value (HL) represents a direct hardness value that is automatically converted to other hardness units of your choice such as Brinell, Vickers, Rockwell and Shore. Both the HL value and another selected hardness unit are displayed on the unit screen simultaneously.

Selecting the impact device type

We offer 6 (six) impact devices being that each one of them is different and ideal for specific applications. In this section we offer general information including measuring ranges and recommended applications for each impact device type.

Please see figure 2 below for a representation of the physical aspect of each one of the impact devices that we offer.




Figure 2: Available impact device types for QH5 units

Impact device type D

This is a “universal” type impact device because it covers the widest range of hardness units, hardness ranges and materials available on QH5 hardness tester which also means that you will cover the widest range of applications.

Impact device type DC

The only difference between a type DC and a type D impact device is that the body on a DC impact device is 86mm long or half the length of a type D impact device making it ideal for measurements in hard to reach places. Unlike all other impact devices that are spring loaded type DC impact devices are loaded manually.

Impact device type DL

The long and thin “needle type” tip allows DL impact devices to work in very narrow areas that cannot be measured with any other impact device. This impact device is commonly used to measure hardness in gears.

Impact device type C

Type C impact devices produce the least amount of energy when compared to all other impact devices (up to 25% less than device type D) making it the best choice for measuring superficial hardness and small parts. The lowest impact energy also means the smallest indentation.

Impact device type G

Type G impact devices use a ball that is 5mm in diameter and it also releases the highest impact energy at 90 N*mm allowing it to be used over rough surface finishes such as those found in metal casts.

Impact device type E

While type D impact device measure up to 940HV (Vickers), type E impact devices use a synthetic diamond ball that allows for measurements in hardened or template steel up to 1211HV.

The table below shows detailed technical information on each impact device type.

Impact devices comparison table

Parameter (Unit)	Impact device type					
	D	DC	DL	C	G	E
General characteristics						
Length (mm)	147	86	202	141	254	155
Diameter (mm)	20	20	20	20	20	20
Weight (g)	75	50	100	75	250	80
Max Hardness (HV)	940	940	950	1000	650	1200
Impact device tip (ball)						
Diameter (mm)	3	3	2.78	3	5	3
Hardness (HV)	1600					5000
Material	Tungsten carbide					Diamond

Impact devices comparison table (Continued)

Impact body						
Energy (N*mm)	11	11	11	3	90	11
Mass (g)	5.5	5.5	7.3	3	20	5.5
Surface test piece requirements						
Rugosity ISO	N7	N7	N7	N5	N9	N7
Rugos. RT (μm)	10	10	10	2.5	30	10
Rugos. RA (μm)	2	2	2	0.4	7	2
Minimum test piece weight (Kg)						
Stand alone	5	5	5	1.5	15	5
With solid support	2	2	2	0.5	5	2
Coupled with paste	0.1	0.1	0.1	0.02	0.5	0.1
Minimum test piece thickness (mm)						
Coupled	3	3	3	1	10	3
Surface thickness	0.8	0.8	0.8	0.2	—	0.8
Test piece impact indentation						
On parts up to 300HV						
Diameter (mm)	0.54			0.38	1.03	0.54
Depth (μm)	24			12	53	24
On parts up to 600HV						
Diameter (mm)	0.45			0.32	0.90	0.45
Depth (μm)	17			8	41	17
On parts up to 900HV						
Diameter (mm)	0.35			0.30	—	0.35
Depth (μm)	10			7	—	10

Impact device components

This section provides an overview of basic impact device components.




Figure 3: Impact device components

Figure 3 shows the most important parts that make up an impact device and the procedure used to remove the impact device body. Over time and depending on the number of measurements that you make the impact tip (ball) located on the impact device body will need to be replaced. In order to remove the impact body turn the support ring clockwise (see figure 3-1) until the ring is released and the impact body falls off (figure 3-2). When doing this make sure that you are working on a table where the impact body can fall and not get damaged if hitting the floor. Remove and replace the impact tip (ball) making sure that everything is left clean and repeat the procedure to put the impact body back in place.

Important: Safety information

All QH5 series portable hardness testers are for industrial use only and cannot be used in medical applications. The QH5 operates on two AA size batteries. We strongly recommend that you use only top brand name alkaline batteries.

Disposal of your QH5 and its components must be done in compliance with all applicable regulations.

About the Software

Because of its complexity level, software is never really completely error free. For this reason in software controlled instruments always make sure that the operations required for your application are in correct working order.

Warranty

Demeq provides a 3 year limited warranty on electronic units that is automatically extended to 5 years when you register your unit while a 6 (six) month warranty is offered on impact devices.

Please remember to register your unit at:
<http://www.demeq.com>

Every instrument undergoes thorough testing during manufacturing as well as before shipping. In the event warranty service becomes necessary Demeq and or your local distributor will make every reasonable effort to get your problem resolved in the earliest possible time and when available will offer you a loaner unit while your instrument undergoes repair.

1 First steps

1.1 Know the QH5

1.1.1 Front panel




Figure 1.1: Front of the unit

1. Graphic LCD display with LED backlight illumination
2. Move Left key / View partial statistics (Stat)
3. Move Up key / Manually store a value (Store)
4. Move Right key / Switch to graphical measure mode screen (Graph)
5. Menu key / Enter and exit measure screen / Exit and return to menus (Home)

6. Move Down key / Quick access to memory menu screen options (Mem)
7. Change backlight illumination key (On, Off, Auto)
8. Enter key / Edit values on the measure screen (Edit)
9. The **Q** key: Power On and Shutdown (touch and hold for 2 seconds) / Make quick and short touches to activate special features
10. The **+** key: Direct measure screen access from any menu screens / User selectable functions
11. Horizontal scrolling center point (lock and unlock keypad on measure screen)
12. Vertical scrolling center point (adjust LCD contrast)

1.1.2 Connectors




Figure 1.2: Unit connectors

1. Impact device connector type Lemo 0B
2. USB mini connector to connect to PC using a USB cable

1.2 Install or replace batteries

The QH5 is powered by 2 (two) AA batteries that are placed in the battery compartment located in the back of the unit. To gain access to the battery compartment slide the cover as shown in figure 1.3-1 and gently push the extraction ribbon upward and slightly towards the right to release the batteries (figure 1.3-2).

When you install new batteries, first insert the positive end of each battery so that it coincides with the positive pole inside the battery compartment as you see in figure 1.4-1.

Always leave the extraction ribbon underneath the batteries.




Figure 1.3: Removing batteries





Figure 1.4: Replace / Insert batteries



Notes

Always use new alkaline top brand batteries for extended battery life.

Do not mix new and old batteries. Always replace both batteries.

Rechargeable batteries type NiMH can be used but will result in less time of continuous operation.




Important

Do not remove batteries while the unit is powered as this may affect the Datalogger (See *Appendix: "Additional information, Error Messages"*)

1.3 Connecting the impact device

The QH5 uses a type Lemo 0B 3-pin connector located on top of the unit. All dmq impact devices are provided with Cal-Tag technology allowing you to easily switch or replace impact devices with no need to calibrate the unit. Universal non-brand impact devices can also be used as long as they have the same connector, but dmq does not guarantee their performance.



To connect the impact device simply align the red dot on the male connector with the red dot on the female connector located on the unit and press gently until connected (see figure 1.5)

To release the impact device hold the knurled section on the male connector and gently pull out. Never remove the connector using the cable.

Figure 1.5: Connecting the impact device

1.4 Using the impact device

The procedure explained herein is applicable to all impact device types except for impact device type DC as it does not use a spring loading mechanism.

1.4.1 Loading the impact device

Place the impact device over the surface you want to measure and load by gently pushing the moving body of the impact device in the same direction as the test piece surface. Push the moving body until you reach the bottom limit and then bring the body back to its initial position.

The impact device is now loaded and ready to be used.

1.4.2 Release and measure

Once the impact device has been loaded use one hand to firmly hold the bottom of the impact device (the part that touches the surface you want to measure) against the surface and use your other hand to press the release button located on top of the impact device.

After pressing the button, the impact body will hit the test piece surface and a hardness value will be displayed within a few seconds.


Repeat this same procedure for each measurement.






Important

The Leeb method for hardness testing has requirements and limitations that must be considered in order to obtain reliable and accurate measurements (See *Appendix: "Tips on how to measure correctly"*)

1.5 The “Q” key


The  have three functions:

1. When the unit is off, touch  for 2 seconds to power on the unit.
2. When the unit is on, touch  for 2 seconds to shutdown the unit.
3. With the unit on, making short touches to the  will activate special functions described in each chapter of this manual.

1.6 Display backlight illumination and contrast

Backlight illumination and contrast options can be changed from any screen in the unit.

1.6.1. Display backlight illumination

Touch  to change the backlight illumination.





Figure 1.6: Backlight illumination options

1.6.1. Display contrast



The display contrast on all dmq units is digital. Touch the white dot located in the center of the vertical scrolling bar between the **▲** - **▼** keys and a contrast window will open. Move your finger towards the top and or bottom of the dotted line to adjust the contrast on your display.

Figure 1.7: Display contrast adjustment

1.7 Locking and unlocking the keypad

To lock the keypad place your finger on the white dot located in the center of the horizontal scrolling bar between the **<** - **▲** keys. Move your finger to the right following the dotted line and a window on the unit display will open with the message **Lock** (see figure 1.8). Continue moving your finger in the same direction until you enter blocked mode. The window on the display will close and the blocked keypad indicator will show on the top right of the unit screen.




Figure 1.8: Locking the keypad

Sliding the finger to the left will unlock the keypad.





Figure 1.9: Unlocking the keypad



Important

The keypad can only be locked and unlocked in the measuring screens.

2 Measuring with the QH5

The QH5 can display measurements in 3 numerical measuring modes or screens where each screen shows specific information. To switch screens touch the  key.

2.1 Numerical measure screen (Normal)

2.1.1 Screen mode-1 (Datalogger)





Figure 2.1: Measure screen mode-1

1. Leeb hardness value where L is Leeb and x is the impact device type
2. Datalogger mode indicator: X: Off - M: Manual - A: Auto
3. + (plus) or – (minus) measured value indicator as it relates to the nominal value in differential mode (Page 37)
4. Battery level indicator
5. Hardness value in the selected hardness unit
6. Icon indicating that a value was stored
7. Blocked keypad icon indicator (Page 8)
8. Impact device indicator

9. Impact device angle indicator (Page 16)
10. User selected hardness unit (Page 19)
11. Average hardness value in the hardness unit selected by the user
12. Position of the last stored value (Column, Row)
13. Name of the open file where values are being stored (Page 43)

2.1.2 Screen mode-2 (Material)



14. User selected test piece material (Page 17)

15. Number of (N) values indicator for real time statistics (Page 36)

Figure 2.2: Measure screen mode-2

2.1.3 Screen mode-3 (Statistics)





Figure 2.3: Measure screen mode-3


16. Leeb hardness value where L is Leeb and x is the impact device type


17. Minimum hardness value within the group
18. Average deviation within the group
19. Number of (N) values indicator for real time statistics (*Page 36*)
20. Average within the group
21. Maximum hardness value within the group
22. Range within the group
23. Location within the file of the last stored value


2.2 Keys in numerical measure modes


Keys in all three numerical measure screen modes have the following functions:


 : Touch to generate real time statistics based on the number of (N) stored values at the time this function is activated.

 : Touch to manually store the measurement in the memory.

 : Touch to switch to the real time graphic histogram mode.

 : Touch to exit the measure screen and enter the main menu.

 : Touch to view quick memory access options.

 : Touch to access the select / edit mode. 3 flashing arrows will appear over the fields of angle, hardness unit and material.





Figure 2.4: Measure screen in mode-2 select / edit mode

- To select angle touch (the angle can be changed even while measurements are being made).
- To select hardness unit touch .
- Touch to select material.

Always use the - keys to edit the values in any given field and touch to save.



Notes

The material can only be changed in the numerical measure screen in mode-2 (Page 11).

The angle and hardness unit can be changed in any measure screen mode.

When the hardness unit is changed statistics, graphics and the actual hardness value on screen are set to zero.



: Short touches allow you to switch between the three measure screen modes. Touch for 2 or more seconds to shutdown the unit.



: Changes the backlight illumination.



: Enters the direct access function established by the user.



: Set display contrast.



: Lock and unlock keypad.

2.3 Graphical measure screen (Histogram)

The QH5 allows you to view graphic representations of measured values in real time and in two screen modes.




Figure 2.5: Graphical measure screens (mode-1 and mode-2)

1. Maximum hardness value within the group
2. Minimum hardness value within the group
3. Average within the group

4. Leeb hardness value where L is Leeb and x is the impact device type
5. Hardness value in the hardness unit selected by the user
6. Battery level indicator
7. Impact device angle indicator
8. High alarm indicator (*Page 23*)
9. Graphic of average value within group
10. Low alarm indicator (*Page 23*)
11. Graphic reference value representation in the selected hardness unit
12. Histogram bars that represent individual group values
13. Average deviation within the group
14. Range within the group

2.4 Keys in graphical measure modes



Key functions in the two graphic measure screen modes are the same as in the numerical measure screen modes (*Page 12*) except for the following keys:



: Go to the numerical measure screen mode



: Access the select / edit mode. Touch this key and 2 flashing arrows will appear over 2 fields namely angle and hardness unit.

- To select angle touch  (the angle can be changed even while measurements are being made)
- To select hardness unit touch 







Figure 2.6: Graphic measure screen in select / edit mode

Use the  -  to edit and to save the change in the hardness unit touch .

2.5 Set impact device angle

Hardness measurements can be taken in any direction and the impact device angle needs to be manually set in the QH5. Setting the angle is very important in obtaining reliable readings.









Figure 2.7: Icons corresponding to the impact device angles

The QH5 offers you three ways of setting the impact device angle:





- From the measuring screen touch  to enter the select / edit mode and touch  to select angle. Edit using  and touch  to save.
- Touching the  key as long it was set to Angle in the direct access options that can be set for this key (Page35).
- From the hardness configuration menu under Angle (Page 34).

2.6 Select material and hardness unit





Material and hardness unit options depend on the impact device that is connected to the unit.

Before measuring make sure that the impact device you will be using meets your needs in terms of the material, hardness unit and hardness range in which you want to measure.

The QH5 offers you three ways to change the material:

- On the numerical screen in mode-2 only (Page 11) touch  to enter the select / edit mode and touch  to select the material. Edit using the cursor keys and touch  to save.
- Touching the  as long it was set to Material in the direct access options that can be set for this key (Page 35).
- From the main menu under Materials (Page35).

The QH5 offers three ways to change hardness unit:

- On the numerical measure screen touch  to enter the select / edit mode and touch  to select unit. Edit using the cursor keys and touch  to save.
- Touching the  as long it was set to Unit in the direct access options that can be set for this key (*Page 35*)
- From the main menu under Unit (*Page 22*)

For detailed information as it relates to materials, hardness units and hardness ranges please refer to the tables in the Appendix "Tips on how to measure correctly" (*Page 56.*)

3 Menu system and editing

3.1 Instructions on using the menu system

The instructions explained in this chapter apply to all of the menus in the unit.

To scroll QH5 menu options use the **▲** - **▼** cursor keys. When you reach the end of the menu and move to the next menu option it becomes circular as shown herein.




Figure 3.1: Example of how a circular menu works

To select a menu option touch **↵** and to exit and return to the previous menu touch **🏠**.

To go to the measuring screen touch **🏠** from the main menu, or touch **⊕** from any other menu in the unit.




Figure 3.2: Going to the measure screen


3.1.1 Text Editor


The text editor is used to input, modify and delete; letters, numbers and symbols.



Figure 3.3: Alphanumeric editor screens

1. Selected key
2. Cursor
3. Text to be edited
4. Virtual keyboard

Use the cursor keys on the unit to scroll the virtual keyboard until you find the character that you want to use and touch  to select.

Touch the  key to move to the upper case virtual keyboard and to the numbers and symbols keyboard as seen on figure 3.3.

There are 4 keys that are common to all virtual keyboard screens:




Figure 3.4: Common virtual keyboard keys

1. Move cursor to the left

2. Move cursor to the right
3. Delete character on which cursor is on
4. Enter and exit












Figure 3.5: Quick access keys for the virtual keyboard editor

Touch the  key to open the direct access keyboard to the most commonly used virtual keyboard keys. Each virtual key corresponds to a key on the front panel of the unit as follows:

-  : Move the cursor to the left
-  : Erase the character on which the cursor sits
-  : Move the cursor to the right
-  : Undo
-  : Erase the character to the left of the cursor
-  : Enter and exit

To close the direct access keyboard and continue using the virtual keyboard touch .

3.2 Main menu



The main menu is the first list of options you will see when you exit the measure screen and it includes the most important settings.




Touch  from the measuring screen to access this menu.

Figure 3.6: Main menu

3.2.1 Change hardness unit

Unit:

Touch  on **Unit** in the main menu to open the list of available hardness units.



Use the  -  keys to scroll the menu.

Touch  to select the hardness unit.


Touch  to save and exit this menu.

Figure 3.7: Hardness unit options menu



Notes

The units in (Figure 3.7) are for type D impact devices. Remember that the hardness units displayed depend on the impact device that is connected to the unit (Page 56).


Hardness units HU1 and HU2 are user units (Page 37).


3.2.2 Alarm Settings

Alarms

The QH5 has high and low alarm conditions that alert the operator when the measurement is greater than the value set for the high alarm and or when the measurement falls below the value set for the low alarm.

Touch  on **Alarms** to open the alarm menu options.



Touch  on **High** or **Low** to open the numbers editor where you can set alarm values using the cursor keys.


Touch  to save the alarm value that you entered and to return to the previous menu.

Figure 3.8: Alarm menu options

Alarm types that you can choose include:

Beep: Audible intermittent alarm type.


Screen: Visible alarm that causes measurements to be displayed in dotted instead of regular numbers.

Light: Visible alarm that activates the display backlight illumination causing it to flash.


3.2.3 Set histogram range

Histo Range

Here you can set high and low values (hardness range) that will be represented on the vertical axis of the histogram.






Set histogram range menu



Range view in graphic mode


Figure 3.9: Set histogram range values

Touch  on **Histo Range** to open the histogram menu.


Touch  on **High** or **Low** to open the numbers editor where you can set values using the cursor keys and touch  to save the new value and return to the previous menu.

3.2.4 Select language

Language

Touch  on language (which is also identified with a flag) to view available language options.



Use the cursor keys to navigate available language options and touch  to select.




Touch  to save and exit this menu.


Figure 3.10: Language menu options


3.2.5 Unit information

Unit Info

Select **Unit Info** to view information including owner data as well as the software version that your unit is running.

To switch between unit information screens touch the  -  keys.

To return to the main menu touch .





Note

The information required to obtain model upgrade licenses is included in this option.


3.3. General configuration options

Configure

Touch  on the **Configure** option to open the general configuration options menu.



Use the  -  keys to scroll the menu.

Touch  to select any of the menu options.


Touch  to exit and to return to the previous menu.

Figure 3.11: General configuration options menu

3.3.1 Set time and date

Set Clock



Choose **Set Clock** to open the time editor and use the cursor keys to set the time. Touch  to save and to enter the date editor screen. After you change the date touch  to save and exit.




Figure 3.12: Time and date edit screens

3.3.2 Set time and date format

Clock Format

Choose **Clock Format** to open the menu that allows you to set the time format (12Hs or 24Hs) and the date format (D/M/Y – M/D/Y).









Touch  on the option you wish to select and touch  to save and exit.

Figure 3.13: Date and time format menu options

3.3.3 Set keypad sensitivity

Key Sense:

This option allows you to set the keypad sensitivity. The number that you set here has a direct relationship to the keypad sensitivity. A higher number means a more sensitive keypad.

Touch  on **Key Sens.** and use the  -  keys to change the keypad sensitivity. Touch  to save and the keypad will already be working with the new sensitivity level.





Figure 3.14: Key sensitivity setting and confirmation screens

To confirm the change in sensitivity touch . If you touch any other key or the on-screen counter reaches 0.0, the sensitivity will return to its previous setting.

The factory default setting is 50. Under special conditions we suggest that the sensitivity level be changed.



Tips

If the unit will be operated using security gloves we recommend that the sensitivity level be raised.


To make the keypad “harder” simply lower the sensitivity level.

In applications where the front of the unit may be exposed to water and/or vapors the sensitivity should be lowered.

3.3.4 Set auto-off time

AutoOff:

The unit will shutdown automatically if no key is touched or no measurement is made after a time set by you.

Touch  on **AutoOff** to set the time before the unit automatically shuts down.



Touch the  -  keys to set the time and touch  to save and exit.




Touch  to exit without making changes.

Figure 3.15: AutoOff time setting screen

3.3.5 Adjust display contrast

Contrast:

Contrast settings allow you to turn your screen lighter or darker where 1 is the lightest and 32 is the darkest.

Touch  on **Contrast** and use the  -  keys to change the contrast on your screen.

Touch  to save or touch  to exit without making changes.






Figure 3.16: Screen contrast settings




Tips

Contrast on LCD screens can change with temperature. Use the contrast option to compensate for changes caused by temperature to maintain optimal viewing conditions.

3.3.6 Beep Activation

Beep


Beep refers to the sounds that the unit makes when keys are touched and when the audible alarm is active.

Touch  to enable or disable the beep option.

3.3.7 Introduction screen

Intro



The introduction screen is the first screen that you see after the unit is turned on and includes owner information such as name, telephone number and e-mail.

Touch  to enable or disable this option.

3.3.8 Owner information

Set ID

This option allows you to enter owner information (the info that would appear on the introduction screen).

Touch  on **Set ID**, enter the password (the factory default password is 12345) and touch  to access user info menu options.




Figure 3.17: Enter password to access the user info menu

The user information that can be changed includes the following:

Name: Set or change the owner name.

Phone: Set or change the telephone number.

Name@: Set or change the e-mail (before the @).

@Domain: Set or change the domain for the e-mail (after the @).

Edit Pass: Allows you to change the password needed to access this menu.



Notes

To set or change text see page 20.

When showing user information, the e-mail address is displayed as "Name@Domain".





Important

The factory default password is 12345. You can change this password after adding your user information.

3.3.9 Lock configurations

Locks

Certain configuration options on your QH5 so as to avoid unwanted changes. Use of the locking options allow a supervisor to optimize unit configuration settings required for a specific test and then pass the unit on to an operator for him or her to conduct actual measurements knowing that the unit has been properly configured and that specific settings cannot be changed.

Touch  on **Locks**, enter your password and then touch  again to view the configuration options that can be locked.




Figure 3.18: Enter password and options lock menu

Each option is followed by a lock indicating whether the feature is locked (closed lock) or unlocked (open lock).

Touch  on each of the following options to lock or unlock:

Configure: Lock or unlock hardness configuration options (Angle, Material, Hardness unit).

DataLogger: Lock or unlock Datalogger configuration options.

3.3.10 Model upgrade licenses

Licenses

If you purchased a QH5 D and need to use an impact device other than a type D you can always upgrade to a QH5 M with the purchase of a software upgrade license and the impact device that you need. When and if you need to upgrade we will ask for the following:

- Unit model
- Unit serial number
- Type of license (G or M)







Touch  on **Licenses** to view all licenses available for your unit (checkmarks indicate active licenses).

Figure 3.19: Licenses screen

To enter the new license number that you purchased touch  or to exit and return to the previous screen touch .





Use the cursor keys to enter the license number and touch  to save.

Figure 3.20: Enter license screen

After you enter the new license number the unit will respond with one of the following messages:



Wrong license password message



Correct license password message

Figure 3.21: Response messages after a license is entered

If the license number that you entered is correct the unit will show an updated license screen where the newly purchased license appears followed by a checkmark.



Important

Upgrading a QH5 to use a type G impact device you must purchase an HLG test block, when upgrading a QH5 to use type C or DL impact devices request HLD test block conversion values.

3.3.11 Return to factory default settings

Set Default

Choose **Set Default** to return to the original factory default general configuration options.

Touch  and a confirmation screen will appear.






Touch  to confirm and return to the previous menu or touch  to exit without making changes.

Figure 3.22: Set factory default settings confirmation screen

3.4 Measuring configuration options

Hardness




Select **Hardness** from the main menu to display measuring configuration options.


Correctly setting these options is critical in obtaining reliable hardness measurements.

Figure 3.23: Measuring configuration options menu

3.4.1 Set impact device angle

Angle:

Touch  on **Angle** to select the angle in which the impact device will be used.



Use the  -  keys to scroll all menu options and touch  to select.



To exit without making changes touch .

Figure 3.24: Set Impact device angle menu

The angle you select here will also show on the measuring screen with the corresponding icon.

3.4.2 Select material

Material

Touch  on **Material** to select the material that you will be measuring. The options available in this menu will depend on the impact device connected to the unit (Page 56).



Use the  -  keys to scroll all menu options and touch  to select.




To exit without making changes touch .

Figure 3.25: Materials menu

3.4.3 The "Plus" key



In the measuring screen the  is used to quickly access any of the options below as configured by you.





Touch  on  to open all quick access options.

Figure 3.26: Quick access options menu for the "Plus" key

Quick access options that can be set for the  key are:

Angle: To change the impact device angle.

Unit: To change the hardness unit.

Store: To manually store measurements using this key.


Go to Grid: Touch to go to the grid in the open file.




3.4.4 Set group (N) number


Group (N):

In order to obtain reliable measurements with your QH5 we recommend that you take at least 3 (three) measurements within 3 to 4mm from one another and use the average value as your final hardness measurement. The number of measurements before an average is closed is set as an (N) number of values.

The Group (N) number is also used for statistics as well as for setting the number of columns / batches in the Datalogger so for every (N) number of values statistical data is automatically updated and a group is closed in the Datalogger.

Partial statistics can be viewed at anytime by touching the  key.

Touch  on **Group (N)** to open the numbers editor where you can set the (N) number. Touch  to save or touch  to exit without save.




Note

Every time a hardness unit is changed the group (N) number is reset to zero and the group that was open in the Datalogger is closed for a new group to automatically open.

3.4.5 Select measure mode

Measure:

Touch  on **Measure** to open the measure modes options menu.




Figure 3.27: Measure mode options menu and set nominal value



The modes in which measurements are represented are:


Absolute: The unit displays the real measured value.

Differential: The value displayed is a result of the value obtained from calculating:

$$\text{Differential} = \text{Real value} - \text{Nominal value}$$

The nominal value is a reference value for the test piece.

Touch  on **Nominal** to set this value and touch  to save.


To exit without making any changes touch .

3.4.6 Create custom or user units

Custom Units

The QH5 allows you to create two custom or user units to measure materials such as special alloys that are not included in the QH5 materials menu. Custom or user units are defined by using at least 2 (two) reference test piece samples of known hardness values.

In order to create a user unit you need to choose a material from the QH5 materials menu that best matches the material that you will be measuring and you also need to choose a hardness unit.





After selecting the material and hardness unit touch  on **Custom Units** to view the menu for User Unit 1 and User Unit 2.

Figure 3.28: User Unit 1 or User Unit 2 menu

Choose one of the user units touching  and enter the first reference point:






Figure 3.29: First user unit reference point


To enter the first reference point you must make (N) number of measurements on the test piece of the custom material with a known hardness value.


Two options will appear on your unit screen:


N=0: Use the  key to reset the counter to 0 if a wrong measurement was taken.

Angle: Use the  key to change the impact device angle.

Each measurement will appear on the unit display with large numbers until the N number of samples is completed. When this happens an \bar{x} symbol will appear indicating that the value on screen is the average of the N measurements. Right below the average value the number that appears after **Y1=** can be changed to match the known hardness value of the test piece sample.


When you touch  the new reference point will be saved and the menu will change giving you two new options:

Other: Touch  to add another reference point to the newly created unit.

Ready: Touch  to finish the process for creating a new user unit.

User units created with one reference point are precise for hardness measurements for test pieces having similar hardness values to that of the sample used to generate the reference point.

In order to extend the measuring range on a custom or user unit you should use at least two test piece samples of different and known hardness values to create two or more reference points.

Touch  for **Other** and the following screen will open:





Figure 3.30: Second user unit reference point

To enter the second reference point, follow the same procedure that you used to enter the first reference point.

User units are called HU1 and HU2. In the hardness unit selection menu, newly created user units will be followed by the hardness unit that they are based on. So if for example HU1 was created using the Rockwell C (HRC) hardness unit, HU1 will be displayed as HU1 (HRC). When HU1 or HU2 are available they won't show a hardness unit.



Notes

When a user unit is created using two reference points the first point must be of a lower hardness value than the second point or the operation will be automatically cancelled.

Measurements done with user units will only be displayed in the same hardness unit that was used to create the user unit. So for a user unit HU1 (HB) hardness values will be displayed only in HB or Brinell.

User units are only available for the material in which they were created so if a user unit was created using steel, changing to another material will cause the user unit to display as (Empty).

The (N) number of values used to generate reference points is set in Group (N) (Page 36).





Important

Because user units are created to measure uncommon materials and alloys they are approximate measurements that can present a greater degree of error when compared to the predetermined materials in the QH5. To know how precise a user unit really is you should work with several test piece samples of known hardness values that when measured should give you the approximate same error. This error now becomes a known variable.

3.4.7 Select impact device type

Device:

Touch  on **Device** to open the impact device options menu. The options displayed in this menu will depend on your QH5 model. In order for you to better understand unit models, impact devices, materials, hardness units and hardness ranges refer to page 56.



Use the  -  keys to scroll all menu options and touch  to select.


To exit without making changes touch .

Figure 3.31: Impact device menu options

When you select **Auto** the impact device type that is connected to the unit is automatically detected through CalTag technology available in all dmq impact devices.

Generic impact devices can be used on dmq units but the impact device type must be selected manually. When you do a manual

selection make sure that the selected impact device corresponds to the impact device that is connected to the unit.

3.4.8 Set alarm for impact device tip

Tip Alarm

The tip of the impact device body has a tungsten carbide ball that is subject to wear. If you get erroneous readings check the ball for signs of wear or damage / deformation and or measure using the supplied test block. We recommend that you check the unit accuracy every x number of impacts set by you in the **Tip Alarm** option. When the automatic counter in your QH5 reaches the number of impacts set by you and alarm will set off.



Select **Every:** to set the number of impacts (default is 500) and use **Reset** to set the counter back to zero each time the ball is replaced or the impact device is changed.

Figure 3.32: Set impact body tip alarm

3.4.9 Return to factory default settings

Set Default

Choose **Set Default** to return to the original factory default hardness configuration settings.

Touch  and a confirmation screen will appear.





Touch  to confirm and return to the previous menu or touch  to exit without making changes.

Figure 3.33: Set factory default confirmation screen

4 Using the Datalogger

4.1 Understanding how data is organized

In order to optimize the use of the Datalogger in your QH5 it is important that you understand how data is organized.

In the QH5 data is stored in 8 individual files with alphanumeric names. Each file contains a grid with columns and rows. And each grid contains columns (identified with consecutive letters; A, B, ...AA, AB...) that store an "N" number of values or measurements (group). Each value is identified with a column letter and a row number.





Figure 4.1: How data is organized in the Datalogger

In the above grid structure individual values are stored in a "Column (Batch), Row (Cell)". So for example C,4: 764 HL means this value is located in Column C and Row 4. Column or Batch sizes can be set in the Group (N) option (Page 36) so that each time this "N" number is reached, a batch is closed and a new one is automatically opened. Every time the Group (N) number is changed, the number of values in each batch also changes without closing the file. This allows you to have different size batches within the same file.

4.2 Memory menu


Memory



Select **Memory** from the main menu to view all menu options for the Datalogger. This chapter explains how to create, organize, and view files.

Figure 4.2: Memory menu

4.3 Create a file

Touch  on **Files** and use the cursor keys to navigate the list of files in the unit.





Figure 4.3: Creating a file

Select a file that appears as **Empty** (available file) and touch  to name the file with up to 10 alphanumeric characters.

After you enter a name a checkmark will appear next to it meaning that a new file has been created and is ready to be used.

Remember that only one file can be open at any given time so whenever a new file is created, if a file was already open, the file that was open will be closed. Once a file has been closed, it cannot be reopened and new values can no longer be stored. In closed files, values can only be viewed.

Whenever you create a new file, and another file is already open, a warning screen will ask if you want to close the last file.



Touch **<** to confirm that you want to close the open file to create (open) a new one or touch **>** to cancel and return to the menu.

Figure 4.4: Close file confirmation screen

4.4 Actions over single files


Touch **↶** on any file that is not empty and a menu will open with all of the options of what you can do that file.



Figure 4.5: Individual file menu options

4.4.1 View data in a single file

View Data



	A	B	C
1	765	761	765
2	763	764	763
3	764	764	765
4	762	765	764
5	764	766	---
6	763	766	---
7	763	767	---
8	765	HL	---






Touch  on **View Data** to view the contents of the file. Touch  to exit the file.

Figure 4.6: File view in grid format

To move inside the grid use the cursor keys and touch  to jump to the last column that contains data.



Touch  on a value to open a histogram that includes that same value as well as the values included in the foregoing cells within that column.






Touch  to exit and return to the grid.

Figure 4.7: Columns histogram

High and low hardness alarms appear in the histogram as dotted horizontal lines.

4.4.2 The Q key in a grid

Touch  to open the quick access menu that allows you to go directly to a position inside the grid.

Select the **Row**, **Column**, and **Cell** using the  -  -  keys.







Figure 4.8: Quick access menu options in a grid

Row: Enter a row number using the cursor keys so that when you touch  the grid will position itself directly on that row.

Column: Enter the column letter using the cursor keys so that when you touch  the grid will position itself on that column.

Cell: This is a combination of (column and row) so that you can go to a specific cell after you enter the row number and column letter.

4.4.3 The Q key in a histogram

Touch  in the histogram to open the quick access menu that allows you to obtain statistical information on the group of values being displayed.




Figure 4.9: Quick access menu options in a histogram


Error: Displays the number of errors and error percentage values in the batch based on the high and low alarm settings.

Stats: View statistical information for the batch including Min., Max., Range and Mean values

Stats+: View the standard deviation and the percentage (coefficient variation) for the batch.


4.4.4 Send data from a single file

Send

Touch  on **Send File** to send (units with Datalogger only) a single file to a PC using Windows HyperTerminal, or to a printer using an RS232 connection. This option does not work in USB mode.


4.4.5 Rename a file

Rename

Touch  on **Rename** to open the text editor that allows you to change the file name.

4.4.6 View file size

Size

Touch  on **Size** to view the number of stored values within a single file (and the size of the file as a percentage of total unit memory). You can also view the date and time in which the file was created.

4.5 Actions over all files

For all





Touch  on **For all** to open the menu for actions that will affect all files stored in the unit memory.

Figure 4.10: Actions over all files menu

4.3.1 Send all files

Send all


Touch  on **Send All** to send (units with Datalogger only) all files stored in the unit memory to a PC using Windows HyperTerminal, or to a printer using an RS232 connection. This option does not work in USB mode.

4.3.2 Erase all files

Erase all

The **Erase All** action permanently deletes all files stored in the unit memory and recovers 100% of the memory capacity.

Before files are deleted, a screen will be displayed asking you to confirm or to cancel this action.



Touch **>** to cancel and return to the previous menu or touch **<** to begin deleting all files.

Figure 4.11: Erase all confirmation screen

When the erase all action has been confirmed the following screens will be displayed:




Figure 4.12: Erase all progress screen

4.6 Quick memory menu (Mem key)

Touch **V** on the measuring screen to open the quick memory menu.



Figure 4.13: Quick memory menu options

In each quick memory menu screen three options are displayed. To access these options use the **<**, **^**, **>** keys. To change memory screens use the **V** key as seen on figure 4.13.

Options in the first quick access memory screen:

Label: Allows you to tag a value with a number from 0 to 65535 so that it can be easily identified in the grid that you open in DataCenter. Tags are not seen in the grids displayed in the unit.

Close: Closes the current file and opens a new one.

Delete: Delete the last stored value.

Options in the second quick access memory screen:


Time: Inserts the time when the value was stored.

Auto: Activates the auto capture mode.

Manu: Activates the manual capture mode.

4.7 Connect to PC with DataCenter

Connect:

Touch  on **Connect** to enter the "Waiting: USB" mode.

Touch  to exit and cancel the connection.




Figure 4.14: Connecting to a PC


With the unit in waiting to connect make sure that the USB or the RS232 cable is properly connected to both the unit and the PC and click on the <Connect> icon in DataCenter.

When a successful connection is established the files in your unit memory will appear in DataCenter. To view their contents simply double click on each file.

For additional information on dmq DataCenter software please visit <http://www.demeq.com>

4.8 Datalogger Configuration

Configure




In the memory menu touch  on **Configure** to open the Datalogger configuration options menu.

Figure 4.15: Datalogger configuration options menu

4.8.1 Configure communications

The first two options in the configure Datalogger menu are **Mode** and **Send** which allow you to select how the unit will communicate with a PC or a printer.





Figure 4.16: Configure communications options

Touch  on Mode to select the type of connection.

USB: Select USB to connect to a PC using a USB cable (included). You must already have DataCenter installed in your PC.

RS232: Select RS232 to connect to a PC or a printer using an RS232 cable (optional).

Touch  on Send to select whether you will send files to a PC or a printer.

PC: When using an RS232 cable, the unit sends data in an optimal format for Windows HyperTerminal (38400-8-N-1).

Print: Using an RS232 cable and printer, the unit sends data in an optimal format for mini-printers of 40 columns (9600/8-N-1).




Notes

The print option can only be used in RS232. Files cannot be directly sent to a USB printer.

When you use DataCenter to connect your selection of PC or print will not affect communication.

4.8.2 Capture modes

Capture:

Touch  on **Capture** to select the mode in which values will be stored in the Datalogger.





Figure 4.17: Memory capture modes menu

The QH5 has two modes in which to store values

Manual: Touch the  key to store values.

Auto: Every time a measurement is made, the value is automatically stored in the Datalogger. When this option is selected you can also store values when you touch the  key.

4.8.3 Advanced configuration

Advanced











Touch  on **Advanced** to access the advanced configuration options menu for the Datalogger.

Figure 4.18: Advanced configuration options menu

When you enable history the Datalogger will register the unit settings for each measurement that can then be viewed in DataCenter. When history is enabled the unit memory capacity decreases as more data is stored.

Touch  on **History** to enable or disable this option and touch  to exit.

Touch  on **Clock** to set the time and date options that will be recorded by the Datalogger each time a new batch is opened. Touch   to scroll all menu options and touch  to select and exit. Touch  to exit without making changes.

Clock menu options include:

Off: The Datalogger does not record date and time.

Date: Each time a new batch is opened the Datalogger records the date.

Time: Each time a new batch is opened the Datalogger records the time.

Both: Each time a new batch is opened the Datalogger records the date and time.

Tips on how to measure correctly

When selecting the QH5 model that is right for you, you must first choose an impact device type. Select the impact device based on the materials, hardness units, and hardness ranges that you will be measuring by referring to the table below:

Hardness Ranges

Unit	Impact device type					
	D	DC	DL	C	G	E
Steel and cast steel						
HB	80 ~647	80 ~647	80 ~647	80 ~683	90 ~646	83 ~663
HV	80 ~940	80 ~940	80 ~940	80 ~996	—	84 ~1211
HRA	—	—	—	—	—	61 ~88
HRB	38 ~99	38 ~99	38 ~96	—	48 ~100	—
HRC	20 ~68	20 ~68	20 ~68	20 ~70	—	22 ~71
HS	32 ~99	32 ~99	—	32 ~100	—	36 ~103
MPa	275 ~ 2194	275 ~ 2194	275 ~ 2194	275 ~ 2194	305 ~ 2194	283 ~ 2195
Alloy tool steel						
HV	80 ~898	80 ~898	—	—	—	82 ~1009
HRC	20 ~67	20 ~67	—	—	—	22 ~70
Stainless steel						
HB	85 ~655	85 ~655	—	—	—	—
HV	85 ~802	85 ~802	—	—	—	—
HRB	46 ~101	46 ~101	—	—	—	—
HRC	20 ~62	20 ~62	—	—	—	—
Grey cast iron						
HB	93 ~334	93 ~334	—	—	92 ~326	—
Spheroid iron						
HB	131 ~ 387	131 ~ 387	—	—	127 ~ 364	—

Hardness Ranges (continued)

Unit	Impact device type					
	D	DC	DL	C	G	E
Cast aluminum						
HB	30~ 165	30~ 165	—	—	—	—
Brass						
HB	40 ~173	40 ~173	—	—	—	—
HRB	13 ~95	13 ~95	—	—	—	—
Bronze						
HB	60 ~290	60 ~290	—	—	—	—
Wrought copper						
HB	45 ~315	45 ~315	—	—	—	—

The QH5 D only works with type D and DC impact devices.

The QH5 G only works with type G impact devices.

The QH5 M works will all impact devices.

Do not measure over an indentation caused by a previous measurement.

The surface you are measuring must clean and dry.

The minimum surface roughness requirements needed to obtain precise measurements are:

	Impact device type					
	D	DC	DL	C	G	E
Surface condition (rugosity)						
Rugosity	N7	N7	N7	N5	N9	N7
Rugos. RT (μm)	10	10	10	2,5	30	10
Rugos. RA (μm)	2	2	2	0,4	7	2

Do not measure test pieces that exceed the maximum hardness limits of your impact device:

Impact device type	Maximum hardness
D – DC – DL – E	890 HL (68 HRC)
C	960 HL (70 HRC)
G	750 HL (645 HB)

To obtain precise measurements the following minimum mass and thickness requirements must be met:

	Impact device type					
	D	DC	DL	C	G	E
Minimum test piece weight (kg / pounds)						
Stand alone	5/11	5/11	5/11	1.5/4. 9	15/ 33	5/11
With support	2/4.4	2/4.4	2/ 4.4	0.5/1. 1	5/11	2/ 4.4
Coupled	0.1/ 0.22	0.1/ 0.22	0.1/ 0.22	0.02/ 0.04	0.5/1. 1	0.1/0. 22
Minimum test piece thickness (mm / inch)						
Coupled	3/6.6	3/6.6	3/ 6.6	1/ 2.2	10/ 22	3/ 6.6
Superficial	0.8/ 1.76	0.8/ 1.76	0.8/ 1.76	0.2/0. 44	—	0.8/ 1.76

When working with a portable hardness tester you should always average at least 3 measurements (the QH5 does real time statistics) and the measurements must be made at least 3 to 4mm from one another. The results of these measurements should do not differ in more than ± 6 HLD units. If a difference of ± 6 HLD units is obtained check test conditions and measure again.

When measuring on curved surfaces the curvature radius should not go above 0.3mm in both concave and convex angles. Always use supporting rings on non-flat surfaces.




Figure A.1: Measuring on curved surfaces

Control your impact device on a reference test block at least every 500 impacts to check its condition.

Always make sure that the unit has been correctly configured for material, impact device type and impact device angle.

Do not use lubricants or grease in the mechanical parts of your impact device. The impact device is cleaned using the brush included with the unit.

Technical Specifications

Measuring Principle	Impact Leeb Rebound
QH5 D Impact Devices	D, DC
QH5 G Impact Device	G
QH5 M Impact Devices	D, DC, DL, C, G, E
Materials	Steel and cast steel, Alloy tool steel, Stainless steel, Grey cast iron, Spheroid iron, Cast aluminum, Brass, Bronze, Wrought Copper.
Impact Angles	All directions. (manual selection)
Hardness Units	Leeb, Brinell, Vickers, Shore, Rockwell A, B and C.
Resolution (Entire Hardness Range)	Leeb : 1 HL Brinell : 1 HB Vickers : 1 HV Shore : 0,1 HS Rockwell : 0,1 HRA / B / C
Measuring Range	150 HL to 990 HL
Precision	$\pm 0,5\%$ @ 800 HLD (± 4 HLD)
Real Time Statistics	Maximum, Minimum, Medium, Range and Standard Deviation.
Alarms	High and Low. Visible and Audible.
Languages	English, Spanish and Portuguese.
Datalogger	Up to 32500 values in 8 files. Manual and Auto capture modes. Files with alphanumeric names. Date and time registry. Viewable in grids and graphics with real time statistics.

Connect to PC	USB or RS232
Display	Graphical 128 x 64 pixels with digital contrast and backlight. 24mm digits.
Keypad	Touch-Sense keypad with no mechanical parts and sensitivity adjustment.
Battery Life	150 Hr with 2 AA type batteries.
Working Temperature	-10°C to +50°C
Enclosure Size	ABS 78x117x24 mm with rubber sides.
Weight	200g with batteries.

Additional information

To become a part of the dmq family of users and to receive newsletters and promotional offers available only to dmq customers please register your unit.

Unit maintenance

The QH5 was developed and manufactured for years of trouble free operation and even though the unit does not require special care the following precautions should be considered:

- Avoid contact with corrosive and abrasive substances.
- Do not clean the unit with solvents.
- Do not leave the unit display exposed to direct solar light for prolonged periods of time as this could damage the display.
- Remove the batteries if the unit will be stored for an extended period of time.
- Remove the impact device using the connector and not the cable.
- Do not twist or strangle the impact device cable.
- Do not expose the unit to temperatures below -10°C / 14°F or above 50°C / 122°F.

QH5 Accessories

Part No.	Description
QHS101	Type D impact device with CalTag
QHS201	Type DC impact device with CalTag
QHS301	Type DL impact device with CalTag
QHS501	Type C impact device with CalTag
QHS601	Type G impact device with CalTag
QHR101	HLD test block
QHD101	ILAC certified HLD test block
QHR107	Test block HLG
QHD107	ILAC certified HLG test block
QHA012	Set of 12 support rings
QHG005	Coupling paste
QHL010	QH5 D to QH5 M upgrade license
QAC001	USB cable to connect mini-printer
QAI001	Mini-printer with thermal paper

For additional information on accessories please contact Demeq or your local representative.

Error messages

Error messages may eventually open on your unit screen and are informational only.

If one of these messages opens on your display follow the instructions described below and if the problem persists please contact Demeq.



Figure A.2: System error message

Error 1	Internal Error
Cause	Internal Error
Solutions	Shutdown the unit, wait a few seconds, and power back on. Contact dmq.

Error 2	Attempt to store a value over an existing value.
Cause	Improper unit shutdown (Example: Removing batteries) and powering the unit back on to store values in the Datalogger.
Solution	Download Datalogger values to PC or printer and erase memory.

If a message with a different number were to appear please contact dmq.

Proper disposal



English

Consumers are legally required to dispose of batteries at suitable collection points, vending points or dispatch bays. The crossed-out wheeled bin means that batteries must not be disposed of in the household waste. Pb, Cd and Hg designate substances that exceed the legal limits.

Español

Los usuarios estan obligados por ley a depositar las pilas viejas en un punto de recogida adecuado, punto de venta o centro de envio. El contenedor de basura tachado significa que la pilas no deben desecharse en la basura domestica. Pb, Cd y Hg designan sustancias que se encuentran por encima de los valores establecidos por ley.

Deutsch

Verbraucher sind gesetzlich verpflichtet Altbatterien zu einer geeigneten Sammelstelle/Verkaufsstelle/Versandlager zu bringen. Die durchgestrichene Mülletonne bedeutet: Batterien und Akkus dürfen nicht in den Hausmüll. Pb, Cd und Hg bezeichnet Inhaltsstoffe die oberhalb der gesetzlichen Werte liegen.

Français

La legislation exige des consommateurs le depot des piles usees dans un lieu de collecte appropriée, un point de vente ou un entrepot d'expédition. La poubelle barree signifie qu'il est interdit de jeter les piles et les batteries avec les ordures menageres. Pb, Cd et Hg designent les substances dont les valeurs depassent les limites legales.

Italiano

Per legge, i consumatori sono obbligati a depositare le batterie esaurite presso i punti di raccolta, i punti di vendita o i magazzini di spedizioni. Il simbolo del contenitore dei rifiuti sbarrato indica che è vietato smaltire le batterie con i rifiuti domestici. Pb, Cd e Hg indicano le sostanze presenti con valori superiori alla norma.

Our website: www.demeq.com

Our website is a powerful customer support tool where you will find the latest information as it relates to your QH5 including:

- Application notes
- Manuals and brochures
- Firmware and software updates
- Model upgrade license information
- New accessories

Technical support

Our service department is committed to providing prompt and courteous service. Should you encounter any trouble with your QH5 please contact Demeq or your local representative.

