



Instruction Manual

**Basic Line Torque
Sensor
Type 4520A...**

CE

Foreword

This manual applies to the Basic Line Torque Sensor Type 4520A... .

The instruction manual must be kept on hand for future use, and must be available at the site of implementation of the NC joining system, as needed.

The specifications in this manual can change at any time without prior notification. Kistler reserves the right to improve and to change the product for the purpose of technical progress without the obligation to inform persons and organizations as the result of such changes.

Original language of these operating instructions: German

© 2009 ... 2011 Kistler Group. All rights reserved.

Kistler Group
Eulachstrasse 22
8408 Winterthur
Switzerland
Phone +41 52-224 11 11
Fax +41 52-224 14 14
info@kistler.com
www.kistler.com

Product Center
Torque Sensors, NC Joining Systems,
Force-Displacement Monitoring, Test Stand Systems

Dr. Staiger, Mohilo + Co. GmbH
A Kistler Group Company
Maierhofstrasse 35
73547 Lorch
Germany
Phone +49 7172-184 0
Fax +49 7172-184 400
info.staiger@kistler.com
www.kistler.com

Content

1.	Introduction	3
2.	Important Information.....	4
2.1	Disposal Instructions for Electrical and Electronic Equipment	4
3.	Application and Key Features.....	5
4.	Description of the Measuring System	6
4.1	Mechanical Design	6
4.2	Electrical Block Diagram	7
4.2.1	Examples of Application	8
4.3	Electrical Configuration of Speed Measurement	9
5.	Electrical Connections of the Sensor	10
5.1	Plug Connection.....	11
5.1.1	Installing the Signal Lead	11
5.2	Instruction for Electrical Installation	12
5.3	Connecting Cable.....	13
5.3.1	Cable Diagram with Plugs on Both Sides, Article No.: KSM072030-5.....	13
5.3.2	Cable Diagram, Plug (Sensor), open Ends, Article No.: KSM012497.....	13
6.	Mechanical Installation of the Torque Sensor	14
6.1	Possible Installation Type 4520A... ..	15
7.	Mechanical Application and Mechanical Installation of the Torque Sensor Type 4520A.....	16
7.1	Frictional Torque Control in Production	16
7.2	Torque Measuring Shaft Version RA	17
7.3	Supply and Evaluation	18
8.	Static Calibration.....	19
8.1	Construction of a Simple Calibration Device.....	19
8.2	Calculation Example for Lever Arm Length.....	20
9.	Maintenance	21
10.	Repairs	22
11.	Declaration of Conformity	23
12.	Accessories and Ordering Key	24
13.	Index	25

Total Pages 25

1. Introduction

Please take the time to thoroughly read this instruction manual. It will help you with the installation, maintenance, and use of this product.

To the extent permitted by law Kistler does not accept any liability if this instruction manual is not followed or products other than those listed under Accessories are used.

Kistler offers a wide range of products for use in measuring technology:

- Piezoelectric sensors for measuring force, torque, strain, pressure, acceleration, shock, vibration and acoustic-emission
- Strain gage sensor systems for measuring force and torque
- Piezoresistive pressure sensors and transmitters
- Signal conditioners, indicators and calibrators
- Electronic control and monitoring systems as well as software for specific measurement applications
- Data transmission modules (telemetry)
- Electromechanical NC joining modules and force-displacement monitors
- Test bed systems for electric motors and gear units for laboratory, manufacturing, and quality assurance

Kistler also develops and produces measuring solutions for the application fields engines, vehicles, manufacturing, plastics and biomechanics sectors.

Our product and application brochures will provide you with an overview of our product range. Detailed data sheets are available for almost all products.

If you need additional help beyond what can be found either on-line or in this manual, please contact Kistler's extensive support organization.

2. Important Information

2.1 Disposal Instructions for Electrical and Electronic Equipment



Do not discard old electronic instruments in municipal trash. For disposal at end of life, please return this product to an authorized local electronic waste disposal service or contact the nearest Kistler Instrument sales office for return instructions.

3. Application and Key Features

- Measuring ranges from 1 ... 1 000 N·m
- Speed up to 10 000 min⁻¹
- Torque meter with strain gages measuring system
- Wear-resistant transmission of the measuring signal, integrated amplifier
- Measurement of constant and variable torques
- Torque measurement on the rotating shaft
- Integrated speed measurement
- Application in the laboratory, manufacture and quality control
- Great value for money




Fig. 1: Basic Line torque sensor Type 4520A...

4. Description of the Measuring System

4.1 Mechanical Design

Basic Line torque sensors Type 4520A... consist of a base body which contains the measuring shaft. On the measuring shaft there is a torsional section with strain gages and electronics with signal amplifier and A/D transformer. The connection box of the base body contains the stationary electronics for the signal formation. The base body of the sensor offers different assembly positions.




Fig. 2: Mechanical design Basic Line torque sensor Type 4520A...

4.2 Electrical Block Diagram




Fig. 3: Electrical block diagram

4.2.1 Examples of Application

Strict use of electrical isolation for feed and measuring signal.




Fig. 4: Separate speed and measuring supply

Shared access measuring supply for feed and measuring supply.



Interlink the power and measuring supply, evaluation electronic is to be made.




Fig. 5: Power and measuring supply in the evaluation electronic combined

4.3 Electrical Configuration of Speed Measurement



Speed measurement is effected photo-electrically by evaluating the light, which shines through a grid wheel.

A gallium-arsenide light diode serves as transmitter emitting in the near infrared. In a phototransistor the light is converted into an electric signal and after a pulse shaper made available as "open collector" signal. The input current amounts max. 16 mA.




Fig. 6: Electrical block diagram of speed measurement




Fig. 7: Electrical CMOS- or TTL input circuit/optically isolated input circuit

5. Electrical Connections of the Sensor





Fig. 8: Electrical connections

- Shielded lead of 0,14 mm² nominal cross section

5.1 Plug Connection

Pin Allocation of Built-in 12 pin Connector



Function	Pin	Description
Power Supply	F	+U _B 18 ... 26 VDC, power consumption <2 W
	E	GND Reference for U _B and angle signals
Shield	M	In sensor; connected to case
Torque output	C	U _A ±10 VDC at M _{nom} at >2 kΩ 10 VDC at control signal revolution R _{i,C} = 10 Ω, output with short-circuit protection connection to AGND
	D	AGND Reference for U _A
Speed sensor	B	Track A Open collector output Internal 1 kΩ resistance to 5 VDC (pull up), TTL-level
Input 100 % control input	K	Control Off: 0 ... 2 VDC On: 5 ... 30 VDC
	A	KGND Reference for control
	G	Reserved
	H	Reserved
	J	Reserved
	L	Reserved

5.1.1 Installing the Signal Lead

- Do not run the lead parallel to power cables or control circuits.
- Do not place the lead close to equipment producing strong electromagnetic fields, e.g. transformers, welders, contactors, electric motors, etc.
- If such situations cannot be avoided, run the lead inside earthed steel conduit.
- Make a loop in the lead when fixing it at the torque sensor so that it is not damaged by vibration.
- If supply and evaluation unit are galvanically connected, a differential input must be used for the torque signal to prevent that the voltage drop on the 0 V-supply line affects the measured signal.

5.2 Instruction for Electrical Installation




Fig. 9: Electrical installation



- Please ensure correct functioning of the shield for the connection cable!
- To improve the electrical contact area between stator housing base and machine base, it's recommended to remove the anodization of the bottom of the stator housing.

5.3 Connecting Cable

5.3.1 Cable Diagram with Plugs on Both Sides, Article No.: KSM072030-5




Fig. 10: Cable diagram with plugs on both sides

5.3.2 Cable Diagram, Plug (Sensor), open Ends, Article No.: KSM012497




Fig. 11: Cable diagram with cable socket and open ends

6. Mechanical Installation of the Torque Sensor Fehler! Textmarke nicht definiert.

There are different methods of installing the torque sensor, depending on the application.

Since very high lateral forces and bending moments may occur even at small axial displacement, the torque sensor must always be mounted with couplings.

Generally:

- The plant must be secured with a burst protection corresponding to the machine protection law.
- We recommend calculating the shafting according to the torsion- and bending critical speeds. These speeds should be avoided during operation. For a safe operation of the unit we recommend to remain approx. 30 % below or above the critical speeds.
- After installation depending on speed the unit should be balanced according to DIN 2060.
- The machine vibrations should be checked according to VDI 2056.



Literature:

Dubbel pocket book for machine engineering, published by Springer.

F. Holzweißig, H. Dreßig, textbook of machine dynamics, published by Springer.

DIN 2056 evaluation rules for mechanic vibrations of machines.

6.1 Possible Installation Type 4520A...

Torque sensor between drive and brake




Fig. 12: Together with the half couplings the torque sensor forms a full coupling

Couplings compensate for axial-radial and angular misalignment.

The connection of shaft and coupling hub is positively locked by a clamping element.

The torque measuring shaft is only a part of the power train. Radial and torsional vibrations may have a very bad impact on the performance of the torque shaft and the measuring signal.

For that reason the operating speed must not be near the critical speed, either it has to be far underneath or above it.

7. Mechanical Application and Mechanical Installation of the Torque Sensor Type 4520A...

7.1 Frictional Torque Control in Production





Fig. 13: Application example Type 4520A...

7.2 Torque Measuring Shaft Version RA



For the electric connection of measuring shaft and supply- and evaluation unit we recommend to use the shielded signal lead, Type KSM072030-5 with low capacity.

As supply and evaluation unit we suggest the Control Monitor CoMo Torque Type 4700A...
The matching connection cable is Type KSM018538-2,5.

As an alternative solution the units Type 4704A..., model VA 3600 without display can be used.

Assembly set Type KSM035681 as accessories for VA3600 for the connection of the torque measuring shaft Type 4520A... .

The signal lead should not exceed a length of 30 meters. Do not run the lead parallel to power cables or control circuits.

The pin connection is explained in chapter "Plug Connection" of this manual.

On each side of the torque measuring shaft there is a high quality bearing installed. The installation can have any position, however offset couplings must always be applied to balance geometrical errors and keep false loads away from the torque measuring shaft.


Radial, axial, diagonal and angular errors are compensated by:

- Multi-disk couplings, e.g. Type 2303A...
- Membran
- Claw couplings

7.3 Supply and Evaluation

The sensor may only be operated using filtered 24 VDC voltage.

Recommended supply voltage:



Terminal box for Type 4520A...




Fig. 14 Supply circuit and evaluation

8. Static Calibration

This procedure requires the use of a calibration device with a lever arm and weights for producing specific values of torque.


The calibration procedure is as follows:

- Apply the rated value of torque to the torque meter and then remove it again
- Adjust the zero reading accurately
- Apply a known value of torque to the torque meter
- Adjust the displayed reading to the corresponding value

Plotting a calibration curve

- Calibrate the torque meter as described above
- Apply torque in 1/10 steps up to the full rated value and then remove it again in the same way.
- A delay of at least 30 seconds must be allowed between the individual 1/10 steps so that each reading can stabilize before it is recorded.

8.1 Construction of a Simple Calibration Device



K = loose half-couplings

Fig. 15: Calibration device

8.2 Calculation Example for Lever Arm Length

$$L = \frac{M}{m \cdot g}, \text{ whereby}$$

M = Torque
 L = Length of lever arm required
 m = Mass required
 g = 9.80665 m/s^2
 (= standard gravity – varies with location)




Fig. 14: Calculation of lever arm length

Example: $m = 1 \text{ kg}$
 $M_t = 10 \text{ N}\cdot\text{m}$

$$\rightarrow L = \frac{10 \text{ N}\cdot\text{m} \cdot \text{s}^2}{1 \text{ kg} \times 9.80665 \text{ m/s}^2} = 1.0197 \text{ m}$$

9. Maintenance

- Sensors of the Type 4520A... are almost maintenance-free.
- Durability of bearings in rated temperature range is approx. 20 000 hours.
- Durability of bearings in working temperature range is approx. 10 000 hours.
- Renewal of bearings can only be effected at works.
- Precision applications: Yearly calibration of sensor (calibration at works or with adequate calibration device).
- Control correct cable plug position monthly.
- Check cables for damages monthly.
- Annual re-calibration of torsional moment

10. Repairs

Fault	CauseFehler! Textmarke nicht definiert.	Remedy
Shaft stiff to turn	Bearing defect due to a) torsional or flexural vibration b) high axial or radial loads c) worn bearings d) bent shaft	Return to factory
Zero shift less than 2 %	Torsional vibration Torsional shock	The zero reading can be readjusted at the display.
Zero shift between approx. 2 and 5 % of full scale	Sensor wurde überlastet Drehschwingungen Stossmomente	The zero reading can be readjusted once at the display.
Hysteresis between clockwise and anticlockwise torque	Sensor durch hohe Wechsellast oder Drehschwingungen überlastet.	Return to factory

11. Declaration of Conformity

CE-Konformitätserklärung

Hiermit erklären wir, dass die Bauart der nachfolgend bezeichneten Gerätes

Produktbezeichnung:	Basic Line		
Funktion:	Drehmomentsensor		
Typ:	4520A...		
Betriebsanleitung Nr.:	4520A_002-515d	Datenblatt:	4520A_000-765d

auf die sich diese Erklärung bezieht, den wesentlichen Anforderungen entspricht, die in den nachfolgend bezeichneten Richtlinien festgelegt sind:

EG-Richtlinie 2004/108/EG und Änderungsrichtlinien
EMV-Richtlinie 2004/108/EG und Änderungsrichtlinien
EG-Richtlinie 2006/95/EG und Änderungsrichtlinien


Die Konformität wird in Bezug auf folgende angewandte harmonisierte Europäische Normen erklärt

Norm	Normenbezeichnung
EN 61010-1 /202-8/2004-1	Niederspannungs-Richtlinie: Sicherheitsbestimmungen für elektrische Mess-, Steuer-, Regel-, und Laborgeräte
EN 61000-6-3, 2007-9 EN 55011, 2007-11 EN 61000-6-2, 2006-3 EN 61326-1, 2006-10 EN 61000-4-2, 2009-12 EN 61000-4-3, 2008-6 EN 61000-4-4, 2005-7 EN 61000-4-6, 2009-12	EMV-Richtlinie: Fachgrundnorm Störaussendung Wohnbereiche Störaussendung ISM-Geräte, Grenzwertklasse B Störfestigkeit Industriebereiche mit den darin aufgeführten Grundnormen Elektrische Mess-, Steuer, Regel- und Laborgeräte- EMV-Anforderungen
Prüfbericht Nr.:	86232-1-BCD vom 04.01.1999 Fa. ELMAC, Reg. Nr.:TTI-P-G010/98-01, sowie Nachtrag vom 21.01.2010 Fa. Baudisch

Bei einer nicht mit Dr. Staiger, Mohilo + Co. GmbH abgestimmten Änderung der Maschine verliert die Erklärung ihre Gültigkeit.

Bevollmächtigter zur Zusammenstellung der technischen Dokumentation:
 Dr. Staiger, Mohilo + Co. GmbH

Diese Erklärung wird verantwortlich für den Hersteller abgegeben durch:

Vorname, Name, Funktion:	Dipl. Ing. Franz Winter, Geschäftsführer		
Ort:	Maierhofstr. 35 73547 Lorch Deutschland	Datum:	30.03.11 Unterschrift: 

Diese Erklärung bescheinigt die Übereinstimmung mit den genannten Richtlinien, beinhaltet jedoch keine Zusicherung von Eigenschaften.

12. Accessories and Ordering Key

Included Accessories

- None

Optional Accessories

- | | |
|---|-----------------------------------|
| • Female cable connector
with solder lug 12 pin | Type/Art. No.
KSM000703 |
| • Connecting cable, 5 m, 12 pin
– flying leads | KSM124970-5 |
| • Connecting cable, 2,5 m, 12 pin
– CoMo Torque | KSM185380-2,5 |
| • Control Monitor CoMo Torque
evaluation instrument for torque sensors
(see data sheet 4503A_000-595) | 4700A |
| • Connecting cable, 5 m
12 pin neg. – 12 pin pos. | KSM07203-5 |

Ordering Key

Measuring Range in N·m

1	1
2	2
5	5
10	10
20	20
50	50
100	100
200	200
500	500
1 000	1 000

Type 4520A ☐



Ordering Example

Type 4520A10

Torque sensor: Rated torque 10 N·m

13. Index

A

Accessories and Ordering Key	24
Application/Key Features.....	5
Applikationsbeispiele	8

C

Calculation Example for Lever Arm Length	20
Connecting Cable	13
Construction Calibration Device	19

D

Description of the Measuring System	6
Disposal Instructions.....	4

E

Einleitung	14
Electrical Block Diagram.....	7
Electrical Configuration of Speed Measurement	9
Electrical Connections of the Sensor	10

F

Frictional Torque Control in Production	16
---	----

H

help	3
------------	---

I

Important Information	4
Installing the Signal Lead	11
Instruction for Electrical Installation.....	12
Introduction	3

M

Maintenance.....	21
Mechanical Application and Mechanical Installation	16
Mechanical Design.....	6
Mechanical Installation	14

P

Plug Connection	11
Possible Installation Type 4520A.....	15

R

Repairs.....	22
--------------	----

S

Static Calibration.....	19
Supply and Evaluation.....	18

T

Torque Measuring Shaft Version RA	17
---	----

S.I. Instruments
 256 South Rd. Hilton
 South Australia 5033
 Ph (08) 8352 5511

info@si-instruments.com.au
www.si-instruments.com.au